



WAPATO ROADRUNNER (LUST)  
#4-260085



repair of a cathodic protection system that has been found insufficient. Followup on Colville Tribal Purchasing (#4-020001) and eventual approval of its compliance with FNNC #003. UST inspections conducted at the following:

- ▶ Wapato School District 207 (#4-260102): FNNC #013
- ▶ BIA Wapato Irrigation Project (#4-260080): FNNC #014
- ▶ Inland Fruit & Produce Co. (#4-260120): FNNC #015

4. **LUST Sites:** Site visits were conducted regarding LUSTs at Lindsey Lockers (#4-260010), Wapato Shell (#4-260116), Wapato Roadrunner Deli Mart (#4-260085), and Old Riley Kelly Oil (#4-260086). A LUST confirmation letter was sent to Wapato Roadrunner Deli Mart (#4-250085). Some followup work was done on a reported LUST at the Unocal Station #6357 (#4-260008), but the release was hydraulic fluid from a hoist--unregulated. Copies of some missing reports were forwarded by the Warm Springs Tribe, regarding an older LUST at Tribal Garage (#3-700002).
5. **Outreach:** Numerous local calls fielded regarding heating oil tank removal.
6. **Miscellaneous Administrative:**
  - ▶ various EPA meetings: May 7, 22, & 28
  - ▶ preparations for Yakama inspection trip
  - ▶ preparation of April travel voucher and monthly report

cc: Al Knapp, Acting Director, DEHS, Portland Area IHS